

# **Assortment for the workshop**

## **Multibox hexagonal screws DIN 933**

Description: This multi-box contains 660 hexagonal head screws, M 4 to M 8, in zinc-plated steel.

Advantages: For ease of transport and clear arrangement, up to 4 of these multi-boxes can be stowed in the practical multi-box container type MULTIBOX P 1 C.

(F) Info: Hexagonal screws can be found on page 622

	1 5
Туре	Content
MULTIBOX 933	300 screws M 4 (10 - 16 - 20 - 40 mm)
	160 screws M 5 (16 - 20 - 30 - 40 - 50 mm)
	115 screws M 6 (16 - 20 - 30 - 40 - 50 mm)
	85 screws M 8 (16 - 20 - 25 - 40 - 50 mm)



#### Multibox hexagonal screws DIN 933 made of stainless steel

Description: This multi-box contains 260 hexagonal head screws, M 5 to M 10, in stainless steel A2.

Advantages: For ease of transport and clear arrangement, up to 4 of these multi-boxes can be stowed in the practical multi-box container type MULTIBOX P 1 C.

Info: Hexagonal head made of stainless steel are found on page 622

~ ~	1 9
Type (Nox)	Content
MULTIBOX 933 ES	95 screws M 5 (16 - 20 - 25 - 30 mm)
	75 screws M 6 (16 - 20 - 25 - 30 - 40 mm)
	80 screws M 8 (16 - 20 - 25 - 30 - 35 - 40 - 50 mm)
	10 screws M 10 (30 - 40 mm)



## **Multibox internal hexagon socket screws DIN 912**

Description: This multi-box contains 260 hexagon socket screws, M 5 to M 10, in zinc-plated steel.

Advantages: For ease of transport and clear arrangement, up to 4 of these multi-boxes can be stowed in the practical multi-box container type MULTIBOX P 1 C.

inio: riexagon sockei screws can be iouna on page 623		
Туре	Content	
MULTIBOX 912	60 screws M 5 (10 - 20 - 30 mm)	
	80 screws M 6 (20 - 25 - 30 - 40 mm)	
	80 screws M 8 (20 - 25 - 30 - 40 mm)	
	40 screws M 10 (30 - 40 mm)	



## Multibox nuts - washers - spring washers

Description: This multi-box contains 1425 nuts, washers and spring washers for threads M 3 to M 10, in zinc-plated

Advantages: For ease of transport and clear arrangement, up to 4 of these multi-boxes can be stowed in the practical multi-box container type MULTIBOX P 1 C.

into: Nuts, wasner	Into: Nuts, wasners and spring wasners can be found on pages 617-616	
Туре	Content	
MULTIBOX 934	475 nuts DIN 934 (M 3 - M 4 - M 5 - M 6 - M 8 - M 10)	
	475 washers DIN 125A (M 3 - M 4 - M 5 - M 6 - M 8 - M 10)	
	475 spring washers DIN 127A (M 3 - M 4 - M 5 - M 6 - M 8 - M 10)	



#### Multibox nuts - washers - spring washers made of stainless steel

Description: This multi-box contains 735 nuts, washers and spring washers for threads M 3 to M 10, in stainless steel

Advantages: For ease of transport and clear arrangement, up to 4 of these multi-boxes can be stowed in the practical multi-box container type MULTIBOX P 1 C.

Info: Stainless steel nuts, washers and spring washers can be found on pages 617-618

The diamess steel hols, washers and spring washers can be reen an pages of 7 or 6		
Type (No.)	Content	
MULTIBOX 934 ES	245 nuts DIN 934 (M 3 - M 4 - M 5 - M 6 - M 8 - M 10)	
	245 washers DIN 125A (M 3 - M 4 - M 5 - M 6 - M 8 - M 10)	
	245 spring washers DIN 127B (M 3 - M 4 - M 5 - M 6- M 8 - M 10)	



All data are considered to be unbinding reference values. We accept no liability for data selection that is not confirmed in writing. Pressure data refer, if not otherwise indicated, to liquids of Group II at +20°C